



Bridge Inspection Report

SR 29

over

FLYNT CREEK

STONE County

- INSPECTION DATE
10/27/2022
- STRUCTURE NUMBER
310002906600120
- BRIDGE ID
14535



Sufficiency Rating:
66.2

Health Index:
0.00

Status:
OK

Inspected By: Team Leader Tommy Keyes
Kevin Henry, Tommy Keyes,

Inspection Type(s): Routine


Inspection Performed By: State

TABLE OF CONTENTS

	PAGE NUMBER
LOCATION MAP BRIDGE	1
EXECUTIVE SUMMARY	2
NATIONAL BRIDGE INVENTORY	3
ELEMENTS	4
ADMINISTRATION	5
APPROACH	6
DECK	7
SUPERSTRUCTURE	8
SUBSTRUCTURE	9
HYDRAULICS	10
PICTURES	12
GTG LEFT SIDE	22
GTG RIGHT SIDE	23

County:	STONE	Structure Number:	310002906600120	Facility Carried:	SR 29
Inspection Date:	10/27/2022	Bridge ID:	14535	Feature Intersected:	FLYNT CREEK

Location Map



Latitude: 30.870323

Longitude: -89.121189

County:	STONE	Structure Number:	310002906600120	Facility Carried:	SR 29
Inspection Date:	10/27/2022	Bridge ID:	14535	Feature Intersected:	FLYNT CREEK

Executive Summary

After routine inspection, the structure's condition ranges from good to fair.

Approach: The approach to the structure is in fair condition. The roadway has settled at both ends of the structure. Repairs has been made since last inspection. Minor settling at Northwest approach. The Northeast and Southeast bridge end markers are leaning downhill away from the roadway. Markers has been replaced since last inspection. Weight limit signs has been removed sine last inspection.

Channel Beams: The channel beams are in overall good condition. The top flange of the channel beams has an asphalt overlay and couldn't be inspected. Minor flexure cracks in the webs of the channel beams. Minor spall in the channel beam located above pile 6 of bent 1. Small spalls with exposed rebar in the channel beams located above bent 2. Spall with some exposed rebar around the connection bolts of the beams located above bent 2.

Substructure: The substructure is in overall fair condition. The bulkheads at both abutments have moderate to severe decay issues. The timber wingwalls have settled and have minor to moderate decay issues. The decay has allowed fill material to spill through causing roadway settlement. The Southwest wingwall has been replaced. Spall in pile 5 of bent 1. The piles located in bent 2 have minor to moderate waterline abrasion issues.

Channel: The channel has an NBI rating of a 4, which places it in the condition of poor. The upstream and downstream channel banks have slumping issues. The North channel bank at the site has minor erosion and slumping issues. The South abutment is encroached into the channel, and during high water events the North abutment would be exposed to the channel. Grassing in the channel downstream from the structure is restricting channel flow.

Recommendations:

- Spalls in the channel beams need to be patched.(Not complete)
 - Spall in pile 5 of bent 1 needs to be patched.(Not complete)

County:	STONE	Structure Number:	310002906600120	Facility Carried:	SR 29
Inspection Date:	10/27/2022	Bridge ID:	14535	Feature Intersected:	FLYNT CREEK

National Bridge Inventory

IDENTIFICATION						INSPECTIONS	
(1) STATE CODE	284 - Mississippi					(90) INSPECTION DATE	10/27/2022
(8) STRUCTURE NUMBER	310002906600120					(91) DESIGNATED INSPECTION FREQUENCY	24
(5) INV. ROUTE (ON/UNDER)	1	3	1	00029	0	(92) CRITICAL FEATURE INSPECTION	(93) CFI DATE
(2) HIGHWAY AGENCY 06	(3) COUNTY CODE 131					A. FRACTURE CRITICAL DETAIL	N
(4) PLACE CODE	80160					B. UNDERWATER INSPECTION	N
(6) FEATURES INTERSECTED	FLYNT CREEK					C. OTHER SPECIAL	N
(7) FACILITY CARRIED	SR 29					CONDITION	
(9) LOCATION	1.3 MI E SR 149					(58) DECK	7
(11) MILEPOINT 1.281	(12) BASE HIGHWAY NETWORK 0					(59) SUPERSTRUCTURE 7	(60) SUBSTRUCTURE 5
(13A) LRS INVENTORY ROUTE 000000029P	(13B) SUBROUTE NUMBER 01					(61) CHANNEL & CHANNEL PROTECTION 4	(62) CULVERT N
(16) LATITUDE 30.870323	(17) LONGITUDE -89.121189					LOAD RATING AND POSTING	
(98A) BORDER BRIDGE CODE						(31) DESIGN LOAD	2
PERCENT RESPONSIBILITY	(99) BORDER BRIDGE STRUCT					(63) METHOD USED TO DETERMINE OPERATING RATING	1
STRUCTURE TYPE AND MATERIAL							
(43) STRUCTURE TYPE, MAIN							
A) KIND OF MATERIAL/DESIGN: 1 - Concrete							
B) TYPE OF DESIGN/CONSTR: 22 - Channel Beam							
(44) STRUCTURE TYPE, APPROACH SPANS							
A) KIND OF MATERIAL/DESIGN:							
B) TYPE OF DESIGN/CONSTR:							
(45) NUMBER OF SPANS IN MAIN 2	(46) NUMBER OF APPROACH 0					(64) OPERATING RATING	57.6
(107) DECK STRUCTURE TYPE 2	(108A) WEARING SURFACE 6					(65) METHOD USED TO DETERMINE INVENTORY RATING	1
(108B) DECK MEMBRANE 0	(108C) DECK PROTECTION 0					(66) INVENTORY RATING	34.5
AGE OF SERVICE							
(27) YEAR BUILT 1973	(106) YEAR RECONSTRUCTED					(70) BRIDGE POSTING	5
(42) TYPE OF SERVICE ON 1	UNDER 5					(41) STRUCTURE OPEN/POSTED/CLOSED	A
(28) LANES ON 02	UNDER 00					APPRAISAL	
(29) AVERAGE DAILY TRAFFIC 3000	(19) BYPASS DETOUR LENGTH 54					(67) STRUCTURAL EVALUATION	5
(30) YEAR OF AVERAGE DAILY TRAFFIC 2020						(68) DECK GEOMETRY	6
(109) AVERAGE DAILY TRUCK TRAFFIC 9						(69) UNDERCLEARANCES, VERTICAL & HORIZONTAL	N
GEOMETRIC DATA							
(48) LENGTH OF MAX SPAN (ft.) 19	(49) STRUCTURE LENGTH (ft.) 40					(71) WATERWAY ADEQUACY	8
(50) CURB/SIDEWALK WIDTHS (ft.) LEFT 0	RIGHT 0					(72) APPROACH ROADWAY ALIGNMENT	8
(51) BRDG RDWY WIDTH CURB-TO-CURB (ft.)	41					(36) TRAFFIC SAFETY FEATURE	
(52) DECK WIDTH, OUT-TO-OUT (ft.)	42.3					36A) BRIDGE RAILINGS:	0
(32) APPROACH ROADWAY WIDTH (ft.)	47.9					36B) TRANSITIONS:	0
(33) BRIDGE MEDIAN 0	(34) SKEW (DEG.) 0					36C) APPROACH GUARDRAIL:	0
(35) STRUCTURE FLARED 0	(10) INV RTE, MIN VERT CLEAR (ft.) 99.99					36D) APPROACH GUARDRAIL ENDS:	1
(47) TOTAL HORIZONTAL CLEARANCE (ft.)	40.7					(113) SCOUR CRITICAL BRIDGES	5
(53) VERTICAL CLEARANCE OVER BRIDGE ROADWAY (ft.) 99.99						SUFFICIENCY RATING 66.2	STATUS 0
(54) VERTICAL UNDER CLEARANCE (ft.)	N 0					CLASSIFICATION	
(55) LATERAL UNDER CLEARANCE RIGHT (ft.)	N 0					(112) NBIS BRIDGE LENGTH	Y
(56) MIN LATERAL UNDER CLEARANCE (ft.)	0					(104) HIGHWAY SYSTEM OF THE INVENTORY ROUTE	0
PROPOSED IMPROVEMENTS							
(75A) TYPE OF WORK PROPOSED 31	(75B) WORK DONE BY 1					(26) FUNCTIONAL CLASSIFICATION OF INVENTORY ROUTE	07
(76) LENGTH OF STRUCTURE IMPROVEMENT (ft.) 40						(100) STRAHNET HIGHWAY DESIGNATION	0
(94) BRIDGE IMPROVEMENT COST (\$)	46000					(101) PARALLEL STRUCTURE DESIGNATION	N
(95) ROADWAY IMPROVEMENT COST (\$)	200000					(102) DIRECTION OF TRAFFIC	2
(96) TOTAL PROJECT COST	391000					(103) TEMP STRUCTURE	
(97) YEAR OF IMPROVEMENT COST ESTIMATE 2009						(105) FEDERAL LANDS HIGHWAYS	0
(114) FUTURE ADT 3000	(115) YEAR OF FUTURE ADT 2040					(110) DESIGNATED NATIONAL NETWORK	0
NAVIGATION DATA							
(38) NAVIGATION CONTROL 0							
(111) PIER OR ABUTMENT PROTECTION							
(39) NAV VERT CLEARANCE (ft.) 0							
(116) MIN NAVIGATION VERT CLEARANCE, VERT LIFT BRIDGE (ft.)							
(40) NAV HORIZONTAL CLEARANCE (ft.) 0							

County:	STONE	Structure Number:	310002906600120	Facility Carried:	SR 29
Inspection Date:	10/27/2022	Bridge ID:	14535	Feature Intersected:	FLYNT CREEK

Element Inspection

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
16 - Reinforced Concrete Top Flange	Ben.	1558	sq. ft.	1558	0	0	0
510 - Wearing Surfaces		1558	sq. ft.	1558	0	0	0
110 - Reinforced Concrete Open Girder/Beam	Ben.	456	ft.	427	25	4	0
1080 - Delamination/Spall/Patched Area		7		0	3	4	0
1090 - Exposed Rebar		22		0	22	0	0
216 - Timber Abutment	Ben.	104	ft.	0	54	25	25
1140 - Decay/Section Loss		104		0	54	25	25
226 - Prestressed Concrete Pile	Ben.	21	each	13	5	3	0
1080 - Delamination/Spall/Patched Area		1		0	1	0	0
1190 - Abrasion/Wear (PSC/RC)		7		0	4	3	0
234 - Reinforced Concrete Pier Cap	Ben.	129	ft.	129	0	0	0
304 - Open Expansion Joint	Ben.	41	ft.	41	0	0	0
330 - Metal Bridge Railing	Ben.	76	ft.	76	0	0	0
515 - Steel Protective Coating		228	sq. ft.	228	0	0	0
331 - Reinforced Concrete Bridge Railing	Ben.	76	ft.	76	0	0	0

County:	STONE	Structure Number:	310002906600120	Facility Carried:	SR 29
Inspection Date:	10/27/2022	Bridge ID:	14535	Feature Intersected:	FLYNT CREEK

ADMINISTRATION

Structure Assessment

Structural/Functional Classification:	OK	Health Index:	0.00
Sufficiency Rating:	66.2	Replacement Index:	62.5

Proposed Improvements

75A Type of Work Proposed:	31 - Replacement -	94 Bridge Improvement Cost:	46000	\$
75B Work Done By:	1 - Work to be done by contract	95 Roadway Improvement Cost:	200000	\$
76 Length Of Structure Improvement:	40	Ft.	96 Total Project Cost:	391000
Project Notes:	518030.46576025465	97 Year Of Improvement Cost Estimate:	2009	

Original Construction

Project Number:	UNKNOWN	Plans Available:	No
Station:	UNKNOWN		

Site Conditions

Snooper Required:	No	Site Vegetation:	Low
Traffic control required:	None		
Utility Attachments:			
<input type="checkbox"/> Water	<input type="checkbox"/> Sewer	<input type="checkbox"/> Telecom	
<input type="checkbox"/> Gas	<input type="checkbox"/> Electric	<input type="checkbox"/> Other	
Overhead Appurtenances:			
<input type="checkbox"/> Sign Truss	<input type="checkbox"/> Signal	<input type="checkbox"/> Lighting	
<input type="checkbox"/> Utility Line		<input type="checkbox"/> Other	

County:	STONE	Structure Number:	310002906600120	Facility Carried:	SR 29
Inspection Date:	10/27/2022	Bridge ID:	14535	Feature Intersected:	FLYNT CREEK

Approach Report

NBI Info

(36B) TRANSITIONS	0 - Does not meet acceptable standards/safety feature is required
(36C) APPROACH GUARDRAIL	0 - Does not meet acceptable standards/safety feature is required
(36D) APPROACH GUARDRAIL ENDS	1 - Meets acceptable standards
(72) APPROACH ROADWAY ALIGNMENT	8 - Equal to present desirable criteria

Approach

Appr Guardrail-rear Left Position	Good	
Appr Guardrail-rear Right Position	Good	
Appr Guardrail-forward Left Position	Good	
Appr Guardrail-forward Right Position	Good	
Appr Roadway Condition	Good	
Appr Roadway Transitions	Good	The roadway is settling at both approaches. Has been repaired since last inspection. Minor settling at Northwest approach.

Signage

End Of Bridge Markers	Good	
Vertical Clearance Signing	NA	
Posting Sign - Rear		Since has been removed since last inspection.
Posting Sign - Forward		
Posting Values Correct		
Valid Posting Limits		

County:	STONE	Structure Number:	310002906600120	Facility Carried:	SR 29
Inspection Date:	10/27/2022	Bridge ID:	14535	Feature Intersected:	FLYNT CREEK

DECK

NBI Info			
(58) DECK	7 - Good Condition (some minor problems)		
(036A) BRIDGE RAIL	0 - Does not meet acceptable standards/safety feature is required		
(108A) WEARING SURFACE	6 - Bituminous		
LEFT SHOULDER WIDTH		FT.	
RIGHT SHOULDER WIDTH		FT.	
ASBESTOS DRAINS	U		
DECK AREA	1692	SQ FT.	
Full Bridge			

	<u>Condition</u>	<u>Notes</u>
Structure:	Good	
Wearing Surface:	Good	Asphalt overlay.
Curbs:	NA	
Median:	NA	
Sidewalk:	NA	
Joints:	0	Joints couldn't be inspected due to the asphalt overlay.
Railing:	Good	
Drainage:	Good	
Lighting:	NA	
Utilities:	NA	
Overlay Thickness:	2	in

County:	STONE	Structure Number:	310002906600120	Facility Carried:	SR 29
Inspection Date:	10/27/2022	Bridge ID:	14535	Feature Intersected:	FLYNT CREEK

SUPERSTRUCTURE

NBI Info

(59) SUPERSTRUCTURE 7 - Good Condition (some minor problems)

NUMBER OF BRIDGE PINS

FRACTURE CRITICAL DETAILS None - No FC Details

Full Bridge

CONDITION

	<u>Condition</u>	<u>Notes</u>
Girders:	Good	Very minor flexure cracks in the channel beams. Spall in channel beam above pile 6 of bent 1.
Floor Beams:	NA	
Stringers:	NA	
Steel Risers:	NA	
Bearings:	NA	
Hinge Pins/Hangers:	NA	
Diaphragms/Cross Frames:	Good	Spalls with some exposed rebar around the connection bolts at bent 2.
Paint:	NA	
Collision Damage:	NA	
Deflection/Vibration:	Good	
Cap/Girder Debris:	Good	
Navigation Lighting:	NA	

County:	STONE	Structure Number:	310002906600120	Facility Carried:	SR 29
Inspection Date:	10/27/2022	Bridge ID:	14535	Feature Intersected:	FLYNT CREEK

SUBSTRUCTURE

NBI Info

(60) SUBSTRUCTURE 5 - Fair Condition (minor section loss)

(111) PIER PROTECTION

Abutments

	<u>Condition</u>	<u>Notes</u>
Backwall:	NA	
Bulkhead:	Poor	Moderate and severe decay in both bulkheads.
Wing Walls:	Poor	All timber wing walls are settling, and have decay issues. Southwest wing has been repaired.
Cap:	Good	
Footings:	NA	
Piles:	Good	Spall in pile 5 of bent 1
Embankment:	Fair	Minor slumping and erosion issues.
Slope Paving:	NA	

Full Bridge

	<u>Condition</u>	<u>Notes</u>
Cap:	Good	
Risers:	NA	
Columns/Piles:	Good	Piles located in bent 2 have minor to moderate waterline abrasion.
Footings:	NA	
Web Walls:	NA	
Bracing:	NA	
Pier Protection-Navigation:	NA	
Pier Protection Lighting:	NA	

County:	STONE	Structure Number:	310002906600120	Facility Carried:	SR 29
Inspection Date:	10/27/2022	Bridge ID:	14535	Feature Intersected:	FLYNT CREEK

Hydraulics Report

NBI Info

(61) CHANNEL & CHANNEL PROTECTION 4 - Protect. severely undermined. sev. damage
 (113) SCOUR CRITICAL BRIDGES 5 - Scour within limits of footing or piles
 (71) WATERWAY ADEQUACY 8 - Bridge Above Approaches

Hydraulics

DESIGN MAIN CHANNEL SPAN		CURRENT MAIN CHANNEL SPAN
BANK CONDITION-UPSTREAM	Fair	Minor bank slumping.
BANK CONDITION-SITE	Poor	Minor bank erosion and slumping. The South abutment is encroached into the channel. The North abutment is exposed to the channel during a high water event. With the decay of the timber wing walls, fill material is spilling through and allowing roadway settlement.
BANK CONDITION-DOWNSTREAM	Fair	Minor bank slumping. Grassing in the channel is restricting channel flow.

SCOUR COUNTERMEASURES

<input type="checkbox"/> SPURS	<input type="checkbox"/> BENDWAY WEIRS	<input type="checkbox"/> DROP STRUCTURES	<input type="checkbox"/> HARDPOINTS
<input type="checkbox"/> JACKS	<input type="checkbox"/> LONGITUDINAL DIKES	<input type="checkbox"/> GUIDE BANKS	<input type="checkbox"/> RIPRAP
<input type="checkbox"/> GABIONS	<input type="checkbox"/> CRUTCH BENTS/UNDERPINNING	<input type="checkbox"/> CROSS BRACING	<input type="checkbox"/> SHEET PILE/COFFERDAM
<input type="checkbox"/> DEBRIS DEFLECTORS	<input type="checkbox"/> VISUAL SCOUR MONITORING	<input type="checkbox"/> FIXED SCOUR MONITORING INSTRUMENTATION	

STREAMBED MATERIAL

<input type="checkbox"/> COBBLE/BOULDER	<input type="checkbox"/> GRAVEL	<input type="checkbox"/> SAND	<input checked="" type="checkbox"/> SILT	<input type="checkbox"/> SILT-CLAY
---	---------------------------------	-------------------------------	--	------------------------------------

UNKNOWN FOUNDATION Yes

SCOUR EVALUATION DONE

USGS GAGING STATION None

OBSERVED STREAM VELOCITY Low

STREAMBED AGGRADATION EVIDENT None

STREAMBED DEGRADATION EVIDENT None

ABUTMENTS ENCROACH INTO CHANNEL Yes

INDICATIONS OF SCOUR No

EVIDENCE OF ABUTMENT UNDERMINING No

EVIDENCE OF PIER UNDERMINING NA

INDICATIONS THAT FLOODWATERS OVERTOP BRIDGE No

INDICATIONS THAT FLOODWATERS OVERTOP APPROACHES No

County:	STONE	Structure Number:	310002906600120	Facility Carried:	SR 29
Inspection Date:	10/27/2022	Bridge ID:	14535	Feature Intersected:	FLYNT CREEK

SCOUR NOTES No scour

County:	STONE	Structure Number:	310002906600120	Facility Carried:	SR 29
Inspection Date:	10/27/2022	Bridge ID:	14535	Feature Intersected:	FLYNT CREEK

Pictures



PHOTO 1 Approach
Description Looking South

Pictures



PHOTO 2 Approach
Description Left side looking South

County:	STONE	Structure Number:	310002906600120	Facility Carried:	SR 29
Inspection Date:	10/27/2022	Bridge ID:	14535	Feature Intersected:	FLYNT CREEK

Pictures



PHOTO 3 Channel
Description Looking downstream

Pictures



PHOTO 4 Superstructure
Description Typical cracks in channel beams

County:	STONE	Structure Number:	310002906600120	Facility Carried:	SR 29
Inspection Date:	10/27/2022	Bridge ID:	14535	Feature Intersected:	FLYNT CREEK

Pictures



PHOTO 5 Substructure
Description South abutment

Pictures



PHOTO 6 Substructure
Description South abutment

County:	STONE	Structure Number:	310002906600120	Facility Carried:	SR 29
Inspection Date:	10/27/2022	Bridge ID:	14535	Feature Intersected:	FLYNT CREEK

Pictures



PHOTO 7 Superstructure
Description Typical spalls with exposed rebar

Pictures



PHOTO 8 Superstructure
Description Minor spall in channel beam above pile 6 bent 1

County:	STONE	Structure Number:	310002906600120	Facility Carried:	SR 29
Inspection Date:	10/27/2022	Bridge ID:	14535	Feature Intersected:	FLYNT CREEK

Pictures



PHOTO 9

Channel

Description

Looking upstream

Pictures



PHOTO 10

Substructure

Description

Typical waterline abrasion on piles bent 2

County:	STONE	Structure Number:	310002906600120	Facility Carried:	SR 29
Inspection Date:	10/27/2022	Bridge ID:	14535	Feature Intersected:	FLYNT CREEK

Pictures



PHOTO 11 Substructure
Description North abutment

Pictures



PHOTO 12 Substructure
Description Southeast wing wall

County:	STONE	Structure Number:	310002906600120	Facility Carried:	SR 29
Inspection Date:	10/27/2022	Bridge ID:	14535	Feature Intersected:	FLYNT CREEK

Pictures



PHOTO 13 Channel
Description Looking downstream

Pictures



PHOTO 14 Channel
Description Looking upstream

County:	STONE	Structure Number:	310002906600120	Facility Carried:	SR 29
Inspection Date:	10/27/2022	Bridge ID:	14535	Feature Intersected:	FLYNT CREEK

Pictures



PHOTO 15 Substructure
 Description Spall in pile 5 of bent 1

Pictures



PHOTO 16 Channel
 Description Looking downstream

County:	STONE	Structure Number:	310002906600120	Facility Carried:	SR 29
Inspection Date:	10/27/2022	Bridge ID:	14535	Feature Intersected:	FLYNT CREEK

Pictures



PHOTO 17 Approach
Description Right side looking North

Pictures



PHOTO 18 Approach
Description Looking North

County:	STONE	Structure Number:	310002906600120	Facility Carried:	SR 29
Inspection Date:	10/27/2022	Bridge ID:	14535	Feature Intersected:	FLYNT CREEK

Pictures



PHOTO 19 Approach
 Description Settlement at Northwest corner of bridge

Pictures




PHOTO 20 Substructure
 Description Southwest wingwall

Structure#: 310002906600120
Bridge ID: 14535

County: Stone
Facility: SR 29

Feature Intersected: FLYNT CREEK
Location: 1.3 MI E SR 149




Print Date: 11/2/2022

Structure#: 310002906600120
Bridge ID: 14535

County: Stone
Facility: SR 29

Feature Intersected: FLYNT CREEK
Location: 1.3 MI E SR 149



Print Date: 11/2/2022