

Bridge Inspection Report

US 80

over

CHUNKY RIVER NEWTON County

- INSPECTION DATE 02/14/2023
- STRUCTURE NUMBER 210008005112250
- BRIDGE ID 13542



Suffiency Rating: 62.1

Health Index: 100.00

Status: OK Inspected By: Team Leader Jeff McGee

Taylor Coker, Jeff McGee, Bryan Nutt,

Inspection Type(s): Routine

Inspection Performed By: State


TABLE OF CONTENTS

	PAGE NUMBER
LOCATION MAP BRIDGE	1
EXECUTIVE SUMMARY	2
NATIONAL BRIDGE INVENTORY	4
ELEMENTS	5
ADMINISTRATION	6
APPROACH	7
DECK	8
SUPERSTRUCTURE	9
SUBSTRUCTURE	10
HYDRAULICS	11
PICTURES	12

Inspection Date: 02/14/2023 Bridge ID: 13542 Feature Intersected:

CHUNKY RIVER

Location Map



Latitude: 32.326388 Longitude: -88.922033

Inspection Date: 02/14/2023 Bridge ID: 13542 Feature Intersected:

CHUNKY RIVER

Executive Summary

2023:

DECK:

1.HEAVY DECK SCALING.

2.MOD. DECK CRACKING.

3.DEBRIS IN THE CURBLINE.

4.COMP. JOINTS FAILED AT BENTS 9 AND 10.

5.2 DELAMS AT BOTTOM OF **SPAN 11**, 3' X 2' EACH.

6.1 SPALL AT BOTTOM OF SPAN 12, BENT 13, 2' X 6".

7.NEW STRIP SEAL JOINTS 2023.

SUPER:

- 1.VC AT ABUTMENT AT **BENT 1**, EXTENDS UP THRU CAP ALSO.
- 2.EXPOSED REBAR IN DIA AT BENT 6, SPAN 6, BAY 2, 1'
- 3.BEAM 1 AT BENT 9, SPAN 8 HAS 6' HORZ. CRACK, APPEARS TO GO ALL THE WAY THROUGH.
- 4.VC'S AT THE BACK ENDS OF BEAMS AT SUPERSTRUCTURE, AS LISTED:
- SPAN 2, BENT 2, BEAMS 1 AND 3. REPAIRED
- SPAN 3, BENT 3, BEAM 1.REPAIRED 2023
- SPAN 4,BENT 4, BEAM 3.REPAIRED 2023
- SPAN 4, BENT 5, BEAM 1.REPAIRED 2023
- SPAN 5,BENT 5, BEAMS 1 AND 3.REPAIRED 2023
- SPAN 5,BENT 6, BEAM 1.
- SPAN 8, BENT 8, BEAMS 1 AND 3.
- SPAN 8, BENT 9, BEAMS 1 AND 3. 1 AND 2 REPAIRED AND BEAM 3 HAS SMALL CRACK! 2023
- SPAN 11, BENT 12, BEAM 1.

Inspection Date: 02/14/2023 Bridge ID: 13542 Feature Intersected:

CHUNKY RIVER

• **SPAN 12, BENT 13, BEAMS 1 AND 3**

6.BEAM 2 AT **BENT 10, SPAN 10** HAS 3' HORZ./SHEAR CRACK, APPEARS TO GO ALL THE WAY THROUGH.

7.SPALL IN DIA.2 AT B-11,SPAN 11 1'x2'.

8.BEAM 2 AT B-11 SPAN 11 HAS 2' HORZ. CRACK.

9. HOR. CRACK LENGTH OF BEAM 3 SPAN 12.

10. CHANGED SUPER TO A 3 DUE TO BENTS 9 AND 10.

SUB:

1.EXP. REBAR AT COL 1 AT **SPAN 1,BENT 2**, 3 LOC.

2.4' VC AT COL 2 AT BENT 2, SPAN 1.

3.EXP. REBAR AT COL 2 AT **BENT 4**, ALSO SMALL DELAM.

4.STEEL PLATES OK AT BENT 9.

5.SPALL AT FACE OF CAP AT **BENT 11, SPAN 11**, BEAM 1.

CHANNEL:

1.LOCAL SCOUR AT **BENTS 4-8**, BY COL 1 EACH.

Inspection Date: 02/14/2023 Bridge ID: 13542 Feature Intersected:

CHUNKY RIVER

National Bridge Inventory

National Bridge Inventory						
	IDENTIFICATION				INSPECTIONS	
(1) STATE CODE	284 - Mississippi			(90) INSPECTION DATE	02/14/2023	
(8) STRUCTURE NUMBER	210008005112250			(91) DESIGNATED INSPECTIO	N FREQUENCY 24	
(5) INV. ROUTE (ON/UNDER)	1 2	1 00	0 080	(92) CRITICAL FEATURE INSP	ECTION	(93) CFI DATE
(2) HIGHWAY AGENCY 05	(3) COUNTY CODE	101		A. FRACTURE CRITICAL DI	ETAIL N	
(4) PLACE CODE	93411			B. UNDERWATER INSPECT	TION N	
(6) FEATURES INTERSECTED	CHUNKY RIVER			C. OTHER SPECIAL	N	
(7) FACILITY CARRIED	US 80				CONDITION	
(9) LOCATION	6.2 MI E SR 503			(58) DECK	5	
(11) MILEPOINT 24 243 (12) BASE HIGHWAY NE	TWORK 0		(59) SUPERSTRUCTURE 6	(60) SUBSTRUCTURE 6	

(12) LPS INVENTORY POLITE 00000080P (13R) SURPOLITE NUMBER 1

(13A) LRS INVENTORY ROUTE 000000080P (13B) SUBROUTE NUMBER 1 (61) CHANNEL & CHANNEL PROTECTION 8 (62) CULVERT N

(16) LATITUDE 32.326388 (17) LONGITUDE -88.922033

(98A) BORDER BRIDGE CODE

PERCENT RESPONSIBILITY (99) BORDER BRIDGE STRUCT

STRUCTURE TYPE AND MATERIAL

(43) STRUCTURE TYPE, MAIN

A) KIND OF MATERIAL/DESIGN: 3 - Steel

B) TYPE OF DESIGN/CONSTR: 02 - Stringer/Multi-beam or Girder

(44) STRUCTURE TYPE, APPROACH SPANS
A) KIND OF MATERIAL/DESIGN: 1 - Concrete

B) TYPE OF DESIGN/CONSTR: 04 - Tee Beam

(45) NUMBER OF SPANS IN MAIN 1 (46) NUMBER OF APPROACH 13 (107) DECK STRUCTURE TYPE 1 (108A) WEARING SURFACE 0 (108B) DECK MEMBRANE 0 (108C) DECK PROTECTION 0

AGE OF SERVICE

(27) YEAR BUILT 1929 (106) YEAR RECONSTRUCTED 1992

(42) TYPE OF SERVICE ON 1 UNDER 5 (28) LANES ON 02 UNDER 00

(29) AVERAGE DAILY TRAFFIC 980 (19) BYPASS DETOUR LENGTH 15

(30) YEAR OF AVERAGE DAILY TRAFFIC 2020(109) AVERAGE DAILY TRUCK TRAFFIC 11

GEOMETRIC DATA

(48) LENGTH OF MAX SPAN (ft.) 120.1 (49) STRUCTURE LENGTH (ft.) 534.1 RIGHT .7 (50) CURB/SIDEWALK WIDTHS (ft.) LEFT .7 (51) BRDG RDWY WIDTH CURB-TO-CURB (ft.) 20 (52) DECK WIDTH, OUT-TO-OUT (ft.) 23.6 (32) APPROACH ROADWAY WIDTH (ft.) 29 9 (33) BRIDGE MEDIAN 0 (34) SKEW (DEG.) 0 (35) STRUCTURE FLARED 0 (10) INV RTE, MIN VERT CLEAR (ft.) 99.99 (47) TOTAL HORIZONTAL CLEARANCE (ft.) (53) VERTICAL CLEARANCE OVER BRIDGE ROADWAY (ft.) 99.99 (54) VERTICAL UNDER CLEARANCE (ft.) Ν 0 (55) LATERAL UNDER CLEARANCE RIGHT (ft.) Ν 0 (56) MIN LATERAL UNDER CLEARANCE (ft.)

PROPOSED IMPROVEMENTS

(75A) TYPE OF WORK PROPOSED 31 (75B) WORK DONE BY 1

 (76) LENGTH OF STRUCTURE IMPROVEMENT (ft.)
 663.7

 (94) BRIDGE IMPROVEMENT COST (\$)
 1942000

 (95) ROADWAY IMPROVEMENT COST (\$)
 194000

 (96) TOTAL PROJECT COST
 5422000

 (97) YEAR OF IMPROVEMENT COST ESTIMATE
 2011

(114) FUTURE ADT 990 (115) YEAR OF FUTURE ADT 2041

(59) SUPERSTRUCTURE 6 (60) SUBSTRUCTURE 6

LOAD RATING AND POSTING

(31) DESIGN LOAD 2

(63) METHOD USED TO DETERMINE OPERATING RATING 1

(64) OPERATING RATING 40.1

(65) METHOD USED TO DETERMINE INVENTORY RATING 1

(66) INVENTORY RATING 24.7 (70) BRIDGE POSTING 3

(41) STRUCTURE OPEN/POSTED/CLOSED P

APPRAISAL

(67) STRUCTURAL EVALUATION 5

(68) DECK GEOMETRY 3

(69) UNDERCLEARANCES, VERTICAL & HORIZONTAL N

(71) WATERWAY ADEQUACY 7

(72) APPROACH ROADWAY ALIGNMENT 4

(36) TRAFFIC SAFETY FEATURE

36A) BRIDGE RAILINGS: 0
36B) TRANSITIONS: 0
36C) APPROACH GUARDRAIL: 0
36D) APPROACH GUARDRAIL ENDS: 1
(113) SCOUR CRITICAL BRIDGES 5

SUFFICIENCY RATING 62.1 STATUS 2

CLASSIFICATION

(112) NBIS BRIDGE LENGTH

(104) HIGHWAY SYSTEM OF THE INVENTORY ROUTE 0

(26) FUNCTIONAL CLASSIFICATION OF INVENTORY ROUTE 07

(100) STRAHNET HIGHWAY DESIGNATION 0
(101) PARALLEL STRUCTURE DESIGNATION N

(102) DIRECTION OF TRAFFIC 2

(103) TEMP STRUCTURE

(105) FEDERAL LANDS HIGHWAYS 0 (110) DESIGNATED NATIONAL NETWORK 0

(20) TOLL 3

(21) MAINTENANCE RESPONSIBILITY 01

(22) OWNER 01 (37) HISTORICAL 5

NAVIGATION DATA

(38) NAVIGATION CONTROL 0

(111) PIER OR ABUTMENT PROTECTION

(39) NAV VERT CLEARANCE (ft.) 0

(116) MIN NAVIGATION VERT CLEARANCE, VERT LIFT BRIDGE (ft.)

(40) NAV HORIZONTAL CLEARANCE (ft.) 0

Inspection Date: 02/14/2023 Bridge ID: 13542 Feature Intersected:

CHUNKY RIVER

Element Inspection

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
12 - Reinforced Concrete Deck	Ben.	2895	sq. ft.	2895	0	0	0
16 - Reinforced Concrete Top Flange	Ben.	7793	sq. ft.	0	7793	0	0
1080 - Delamination/Spall/Patched Area		18		0	18	0	0
1190 - Abrasion/Wear (PSC/RC)		7775		0	7775	0	0
107 - Steel Open Girder/Beam	Ben.	486	ft.	486	0	0	0
110 - Reinforced Concrete Open Girder/Beam	I Ken	1217	ft.	1215	2	0	0
1130 - Cracking (RC and Other)		2		0	2	0	0
205 - Reinforced Concrete Column	Ben.	22	each	22	0	0	0
210 - Reinforced Concrete Pier Wall	Ben.	60	ft.	60	0	0	0
215 - Reinforced Concrete Abutment	Ben.	60	ft.	59	1	0	0
1130 - Cracking (RC and Other)		1		0	1	0	0
234 - Reinforced Concrete Pier Cap	Ben.	221	ft.	218	3	0	0
1080 - Delamination/Spall/Patched Area		3		0	3	0	0
300 - Strip Seal Expansion Joint	Ben.	260	ft.	260	0	0	0
311 - Movable Bearing	Ben.	8	each	8	0	0	0
515 - Steel Protective Coating		8	sq. ft.	8	0	0	0
330 - Metal Bridge Railing	Ben.	1070	ft.	1070	0	0	0
331 - Reinforced Concrete Bridge Railing	Ben.	1070	ft.	1070	0	0	0

Inspection Date: 02/14/2023 Bridge ID: 13542 Feature Intersected:

CHUNKY RIVER

ADMINISTRATION

		Structu	ıre Asses	sment				
Structural/Fu	ınctional Classification	: OK		Health Index	:	100.0	0	
Suffiency Ra	iting:	62.1		Replacemen	t Index:	51.5		
		Propose	ed Improv	rements				
75A Type of	Work Proposed: 31 -	Replacement -		94 Bridge Imp	rovement Co	ost:	1942000	\$
75B Work Do	one By: 1 - V	Vork to be done by co	ontract	95 Roadway I	mprovement	t Cost:	194000	\$
76 Length Of	f Structure Improveme	ent: 663.7	Ft.	96 Total Proje	ct Cost:		5422000	
Project Notes	s: 5421613.08966477	712		97 Year Of Im	provement (Cost Es	timate: 2011	I
		Origin	al Constr	uction				
Project Number: FAP-6 REOP				Plans Available: Unknown				
Station:	569+26.5							
		Site	e Conditio	ons				
Snooper Rec	quired: Yes		Site	e Vegetation:	None			
Traffic contro	ol required:							
Utility Attachi	ments:							
	□Water	Sewer		Telecom				
	□Gas	Electric		Other				
Overhead Ap	opurtenances:							
	☐Sign Truss	Signal		Lighting				
	Utility Line			Other				

Inspection Date: 02/14/2023 Bridge ID: 13542 Feature Intersected:

CHUNKY RIVER

Approach Report

NBI Info				
(36B) TRANSITIONS	0 - Does not meet acceptable standards/safety feature is required			
(36C) APPROACH GUARDRAIL	0 - Does not meet acceptable standards/safety feature is required			
(36D) APPROACH GUARDRAIL ENDS	1 - Meets acceptable standards			
(72) APPROACH ROADWAY ALIGNMENT	4 - Meets minimum tolerable limits to be left in place as is			

Approach S Appr Guardrail-rear Left Position Good S Appr Guardrail-rear Right Position Good Appr Guardrail-forward Left Position S Good Appr Guardrail-forward Right Position Good S Appr Roadway Condition Good Appr Roadway Transitions Good

	Signage	
End Of Bridge Markers	Good	
Vertical Clearance Signing	NA	
Posting Sign - Rear	NA	
Posting Sign - Forward	NA	
Posting Values Correct	NA	
Valid Posting Limits		

Inspection Date: 02/14/2023 Bridge ID: 13542 Feature Intersected:

CHUNKY RIVER

DECK

NBI Info

(58) DECK 5 - Fair Condition (minor section loss)

(036A) BRIDGE RAIL 0 - Does not meet acceptable standards/safety feature is required

(108A) WEARING SURFACE 0 - None

LEFT SHOULDER WIDTH .5 FT.
RIGHT SHOULDER WIDTH .5 FT.

ASBESTOS DRAINS U

DECK AREA 12605 SQ FT.

Full Bridge

<u>Condition</u> <u>Notes</u>

Structure: Fair
Wearing Surface: Poor

Curbs: NA

Median: NA

Sidewalk: NA

Joints: Good

Railing: Good

Drainage: Good

Lighting: NA

Utilities: NA

Overlay Thickness: in

Inspection Date: 02/14/2023 Bridge ID: 13542 Feature Intersected:

CHUNKY RIVER

SUPERSTRUCTURE

NBI Info

(59) SUPERSTRUCTURE

6 - Satisfactory Condition (minor deterioration)

NUMBER OF BRIDGE PINS

FRACTURE CRITICAL DETAILS

Full Bridge

CONDITION

Condition Notes Girders: Fair Floor Beams: NA Stringers: NA Steel Risers: NA Bearings: Good Hinge Pins/Hangers: NA Diaphragms/Cross Frames: NA Paint: NA Collision Damage: NA Deflection/Vibration: Good Cap/Girder Debris: Fair Navigation Lighting: NA

Inspection Date: 02/14/2023 Bridge ID: 13542 Feature Intersected:

CHUNKY RIVER

SUBSTRUCTURE

NBI Info

(60) SUBSTRUCTURE 6 - Satisfactory Condition (minor deterioration)

(111) PIER PROTECTION

Abutments

<u>Condition</u> <u>Notes</u>

Backwall: Good

Bulkhead: NA

Wing Walls: Good

Cap: Good

Footings: NA

Piles: NA

Embankment: Good

Slope Paving: NA

Full Bridge

<u>Condition</u> <u>Notes</u>

Cap: Good

Risers: NA

Columns/Piles: Good

Footings: NA

Web Walls: Good

Bracing: NA

Pier Protection-Navigation: NA

Pier Protection Lighting: NA

Inspection Date: 02/14/2023 Bridge ID: 13542 Feature Intersected:

CHUNKY RIVER

Hydraulics Report

			NDI IIIIO			
(61) CHANNEL & CHAN	NEL PROTEC	TION 8 - Banks	are protected			
(113) SCOUR CRITICAL BRIDGES 5 - Scour within limits of footi				3		
(71) WATERWAY ADEQUACY 7 - Slight Chance of Overtopping Bridge						
		H	lydraulics			
DESIGN MAIN CHANNE	L SPAN	9 (CURRENT MAIN CHANNEL	SPAN 9		
BANK CONDITION-UPS	TREAM	Good				
BANK CONDITION-SITE		Good				
BANK CONDITION-DOV	VNSTREAM	Good				
SCOUR COUNTERMEA	SURES	Good				
SPURS	BENDV	VAY WEIRS	DROP STRUCTURES	HARDPOINTS		
JACKS	LONGI	TUDINAL DIKES	GUIDE BANKS	✓ RIPRAP		
GABIONS	□ CRUTO BENTS	CH /UNDERPINNING	CROSS BRACING	SHEET PILE/COFFERDAM		
DEBRIS DEFLECTORS	□VISUAL	SCOUR MONITORI	NG FIXED SCOUR MONITOR	RING INSTRUMENTATION		
STREAMBED MATERIA	L					
COBBLE/BOULDER	GRAVEL	SAND	SILT	SILT-CLAY		
UNKNOWN FOUNDATION	ON					
SCOUR EVALUATION D	OONE					
USGS GAGING STATIO	N		None	None		
OBSERVED STREAM V	ELOCITY		Low	Low		
STREAMBED AGGRAD	ATION EVIDE	None	None			
STREAMBED DEGRADATION EVIDENT			None	None		
ABUTMENTS ENCROACH INTO CHANNEL			No	No		
INDICATIONS OF SCOUR			Yes	Yes		
EVIDENCE OF ABUTMENT UNDERMINING			No	No		
EVIDENCE OF PIER UNDERMINING			No			
INDICATIONS THAT FLO	OODWATERS	GE No				
INDICATIONS THAT FLOODWATERS OVERTOP APPROACHES No						
SCOUR NOTES LO	OCAL SCOUR	AT BENT 5 AND	6			

Inspection Date: 02/14/2023 Bridge ID: 13542 Feature Intersected:

CHUNKY RIVER

Pictures



PHOTO 1 General, Superstructure

Description ELEVS

Pictures



PHOTO 2 General

Description CLE

Inspection Date: 02/14/2023 Bridge ID: 13542 Feature Intersected:

CHUNKY RIVER

Pictures



PHOTO 3 General

Description ELEVN

Pictures



PHOTO 4 Superstructure

Description BEAM END REPAIR B-2

Inspection Date: 02/14/2023 Bridge ID: 13542 Feature Intersected:

CHUNKY RIVER

Pictures



PHOTO 5 Superstructure

Description BEAM END REPAIR B-4

Pictures



PHOTO 6 Superstructure

Description B-8 SPAN 8 BEAM 1 AND 2 REPAIRED

Inspection Date: 02/14/2023 Bridge ID: 13542 Feature Intersected:

CHUNKY RIVER

Pictures



PHOTO 7 Superstructure

Description B-8 SPAN 8 BEAM 3 NOT REPAIRED, CRACK.

Pictures



PHOTO 8 General, Substructure, Channel

Description DS

Inspection Date: 02/14/2023 Bridge ID: 13542 Feature Intersected:

CHUNKY RIVER

Pictures



PHOTO 9 General, Substructure, Channel

Description US

Pictures



PHOTO 10 Deck

Description MOD. DECK CRACKING.

Inspection Date: 02/14/2023 Bridge ID: 13542 Feature Intersected:

CHUNKY RIVER


Pictures



PHOTO 11 Superstructure

Description BEAM REPAIR. BENT 10

Structure#: 210008005112250 County: Newton Feature Intersected: CHUNKY RIVER
Bridge ID: 13542 Facility: US 80 Location: 6.2 MI E SR 503



Print Date: 2/14/2023

Structure#: 210008005112250 County: Newton Feature Intersected: CHUNKY RIVER
Bridge ID: 13542 Facility: US 80 Location: 6.2 MI E SR 503

